



Appl. No. 10/789,237 Response. Dated September 16, 2004 Reply to Notice to File Missing Parts of May 20, 2004


Replacement Sheet 1 of 13







Appl. No. 10/789,237 Response. Dated September 16, 2004 Reply to Notice to File Missing Parts of May 20, 2004 Replacement Sheet 3 of 13



Replacement Sheet 4 of 13







FIG. 6













FIG. 10




Replacement Sheet 9 of 13













FIG. 15

Replacement Sheet 13 of 13

Performance of Series Connected Mixer fIF = 2.1 GHz; PLO = 20 dBm

Power Level [dBm]



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:	
☐ BLACK BORDERS	
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES	
☐ FADED TEXT OR DRAWING	
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING	
☐ SKEWED/SLANTED IMAGES	
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS	
GRAY SCALE DOCUMENTS	
☐ LINES OR MARKS ON ORIGINAL DOCUMENT	
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY	

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.